

Lab Safety Rules



These rules are mandatory. Anyone not adhering to the requirements, will be denied access to the lab. On emergency call: (011) 2583654

Lab. Name: Geotechnical Engineering Lab

Lab. Hazards: Electric Shock, Smoke, Hot Services, Skin Cut, Skin Burn, Fall, Trip, Tangle, Nip Point, Struck.

Personal Protection Equipment PPE	Enforcement
	Gloves Required
	Safety Goggles
	Face Shield
	Safety Shoes
	Lab Coat Required
	Helmet
	Respirator
	Ear Muffs
	No Food or Drinks Required